RESOLUTION NO. $\frac{9-99}{1000}$ CITY OF CENTERVILLE, OHIO

SPONSORED BY COUNCILMEMBER $\underline{J.V. STONE}$ ON THE $\underline{J0}^{++}$ DAY OF JANUARY, 1995.

A RESOLUTION RATIFYING THE ACTION OF THE ASSISTANT CITY MANAGER IN EXECUTING CHANGE ORDERS FOR THE CONSTRUCTION OF THE YANKEE TRACE CLUBHOUSE RESERVING, HOWEVER, TO THE CITY OF CENTERVILLE THE DECISION AS TO WHAT PARTY IS LEGALLY RESPONSIBLE FOR THE PAYMENT OF SAME.

WHEREAS, certain change orders for the construction of the Clubhouse at Yankee Trace Golf Course have been presented to the City of Centerville for approval; and

WHEREAS, the City of Centerville questions its liability for the payment of said change order, but is concerned that the construction schedule proceed without interruption; and

WHEREAS, there is not sufficient time for the City to submit the question as to the liability for the payment of the items in the change order to arbitration;

NOW, THEREFORE,

THE MUNICIPALITY OF CENTERVILLE HEREBY RESOLVES:

<u>Section 1</u>. That the action of the Assistant City Manager in executing the change orders listed in Exhibit A, attached hereto and incorporated herein which action was taken under protest is hereby ratified, reserving, however, the City's right to contest the liability for the payment of said change order.

PASSED THIS 30th day of JANARY, 1995 Centerville, Ohio

ATTEST:

12st Clerk

City of Centerville, Ohio

CERTIFICATE

The undersigned, Clerk of Council of the City of Centerville, Ohio, hereby certifies the foregoing to be a true and correct copy of Resolution No. $\frac{9-92}{3}$, passed by the Council of the City of Centerville, Ohio on the $\frac{3}{2}$ day of $\frac{JHL^{10}RE4}{3}$, $19\frac{43}{3}$.

Clerk of the Conneil assistant

CVILLE\8373.RNF

Municip.: Attorney

YANKEE TRACE CLUBHOUSE

CHANGE ORDERS

DESCRIPTION

· /* - ...*

AMOUNT

Add electrical work for 20 cart chargers	Ś	3,704.41+
Add changing room at pro shop	т	1,236.36+
Reduce window size in office 132		57.80-
Conduit and boxes for additional telephone outlets in pro shop		556.23+
Electrical work for direct buried pump		3,416.44+
Add vent to grease interceptor		258.69+
Revise location of foundation drain at cart ramp		502.95+
Prepare isometric drawing		754.75+
Add steel at academy window		1,353.22+
Revise overhead door at cart ramp		189.79+
Revise door 102A		229.67+
Revise door 125		110.99+
Revise pipe/duct chase at chimney		356.11+
Security system upgrade		3,052.23+
Fire protect structural diaphragm NTE		14,450.00+
Kitchen modifications	1	19,026.44+
Delete stone on gable at north chimney and install EIFS		1,688.32-
Smoke barrier in attic		12,960.97+