

Item C608 – Retrofit Detectable Warning Mat - Special

C608.1 Description

C608.2 Materials and Installation

C608.3 Measurement and Payment

C608.1 Description. Install retrofit Detectable Warning Mats on curb ramps at locations indicated.

C608.2 Materials and Installation. The approved mats (color to be red brick) are:

- Armor-Tile - Surface Applied Systems (rigid, www.armor-tile.com, 800-682-2525)
- ADA Solutions – Surface Applied Systems (rigid, www.adatile.com, 800-372-0519)
- Armorcast (www.armorcastprod.com, 818-982-3600)

The mats shall be 24" long, with varying mat widths depending on the angle and width of the depressed curb and adjacent sidewalk. The mats shall be stored and installed according to manufacturer recommendations, especially the requirements relating to air and surface temperature, surface wetness, and surface cleanliness - before, during, and after installation. The size of the mat installed shall achieve ADA compliance, so the size may vary with varying sidewalk widths.

Some curb ramps have joints or cracks. Mats should not be placed over joints, unless otherwise specified. If mats are placed over joints or cracks, a sealer material shall be used to ensure that water and debris cannot get under the mat. Contact the mat supplier for guidelines.

C608.3 Measurement and Payment. The unit price shall include all materials, equipment, and labor necessary for installation. Any damage to surrounding area must be rehabilitated at contractor's expense.

Payment will be based on the unit price bid:

Item	Unit	Description
C608	Each	Retrofit Detectable Warning Mats